


# Keeping people safe

**Health and safety toolkit** 

# Risk assessment (worked example)



#### **Our Church Risk Assessment**

# Name of church: TBC 30/08/17 Address: Date review of assessment required: 30/08/19 Signed\*:

#### How we carried out the risk assessment

- First of all we looked at information produced by Methodist Insurance to help us understand where hazards could occur in our church. This included their Health and Safety Made Simple Guide, the introduction to this template, and the guidance provided on their website at www. methodistinsurance.co.uk/healthandsafety. We also looked at relevant information provided by the Health and Safety Executive at www. hse.gov.uk
- 2. We discussed if anyone could remember if there had ever been any accidents in the past.
- We then discussed if any other users of the church or anyone who had done work for the church had reported any concerns regarding health and safety.
- 4. We then walked around the church, the grounds and any other buildings we are responsible for and noted anything that might cause harm. We considered how accidents might happen and how serious the outcome of those might be. We noted if there were any precautions in place or any additional ones we could take. If it was possible to eliminate the risk entirely we did this as soon as we could. This was based on what we had learned from the information we had reviewed above (note one).

- 5. We also considered any hazards presented by other activities, such as festivals, concerts or other events including fetes etc. Where these were to be held, we agreed that we would review health and safety precautions before holding the event.
- 6. We recorded the findings of our assessment using this template.
- We communicated the findings to all our employees and volunteers, including anyone new who joins us.
- 8. We have put the risk assessment into practice, making sure that each identified action is progressed and noting when each one is completed on this template.
- 9. We will review and update our risk assessments where we suspect they are no longer valid.

#### **Area assessed:**

# 1. Inside our church

**Internal areas of the church** (for example worship area, meeting rooms, halls and toilets, storerooms, organ lofts, boiler rooms etc.)

#### Who might be harmed?:

Members of the church, employees, volunteers, visitors, ministers, preachers, in fact anyone visiting the church

| What could cause harm?   | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place  | Additional<br>precautions<br>required  | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion<br>date |
|--|--------------------------------|--|--|---------------------------|---|---------------------|--------------------|
| Trips:   |                                |  |  |                           |   |                     |                    |
| Worn or unfixed carpet edges, rugs or doormats     Trailing wires, cables or leads     Worn, damaged or uneven steps or stairs     Poor lighting     Missing or defective handrails     Variations in the level of floors (for example, ramps)     Restricted access including doorway widths     Other.     | Risk <b>√</b><br>N/A           | Carpets in good condition, properly fixed down.  No trailing leads or cables noted. All steps/stairs in good condition. Good lighting levels. Regularly maintained handrails provided. | Replace worn<br>doormat in porch.<br>Inspect floor<br>coverings<br>periodically. | 84                        | 30/08/18                                |                     |                    |
| Slips:   |                                |  |  |                           |   |                     |                    |
| <ul> <li>Smooth floor surfaces,</li> <li>Cleaning activity making floors slippery (for example, wet mopping, use of polishes, etc.),</li> <li>Wet or contaminated floors from poor maintenance (for example, leaking roofs),</li> <li>Spillages of food or drink (particularly in kitchen areas),</li> </ul> | Risk <b>√</b><br>N/A           | No smooth floor surfaces noted. No polishes or wet-mop cleaning undertaken. Matting provided in entrance porch (see above). There are no kitchen areas.                                |  |                           |   |                     |                    |
| <ul> <li>Walk-in contaminant<br/>from adverse weather<br/>(for example, mud,<br/>rainwater, etc.),</li> <li>Other.</li> </ul>  |                                |  |  |                           |   |                     |                    |

| What could cause harm?   | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place   | Additional precautions required   | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|--|--------------------------------|---|---|---------------------------|---|---------------------|-----------------|
| Falls From Height:  When changing lightbulbs  When cleaning or decorating  When putting decorations or displays up  Inadequately guarded balconies or other areas at height  Fragile ceiling material where work or access is required  Damaged ladders, stepladders or other access equipment  Other. | Risk <b>√</b><br>N/A           | Adequate, proprietary stepladder available. Stepladder in good condition/ checked before use. Stepladder properly stored Users know how to use it safely. Information on use available. | Make periodic<br>checks of<br>stepladder.<br>Keep records of<br>checks made.  | 86                        | 30/08/18                                |                     |                 |
| Accumulations of combustible waste     Accumulations of flammable materials     Blocked or obstructed exit routes     Locked escape doors     Portable heaters     Other.  | Risk <b>√</b><br>N/A           | Fire rijk  ASSESSMENT  done. Complies  with guidance  at www.  communities.  gov.nk/fire. All  actions complete  All checks being  completed.  Records  available.                      |   |                           |   |                     |                 |
| Faulty or damaged fixed wiring     Faulty, damaged or unauthorised portable electrical equipment     Faulty or damaged extension cables or adaptors     Other.   | Risk <b>√</b><br>N/A           | Fixed wiring inspected/tested every five years. Completed by a competent electrician. Records of checks made available. Repairs completed by a competent electrician.                   | Implement formal checks of portable equipment. Checks to be made by competent person. Records of checks to be kept. | 68                        | 30/08/18                                |                     |                 |

| What could cause harm?  | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place   | Additional precautions required  | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|---|--------------------------------|---|--|---------------------------|---|---------------------|-----------------|
| Gas:  • Defective or poorly maintained gas boilers or pipework  • Other.  | Risk <b>√</b><br>N/A           | tas boiler is checked/serviced annually. Completed by tas Safe engineer. Records are available. No portable heaters   |  |                           |   |                     |                 |
| Work Equipment:  Defective or poorly maintained power tools (for example, vacuum cleaners, floor polishers etc.)  Defective or poorly maintained hand tools (for example, garden shears, hammers, etc.)  Other. | Risk <b>√</b><br>N/A           | Equipment seen is<br>in good order.   | Implement<br>formal checks (see<br>electricity above).   | Вб                        | 30/08/18                                |                     |                 |
| Asbestos:  In insulation, lagging or fire protection  In wall and roof linings  In organ blowers  In motor housings  Other.   | Risk <b>√</b><br>N/A           |   | Find out if there is as bestoo in the church. Make and keep an up-to-date record of this. Assess the risk from the material Prepare a plan for managing any risk. Implement the steps needed. Review and monitor arrangements put up lace. | 86                        | 30/08/18                                |                     |                 |
| Glazing:  • Non-safety glass in doors, partitions or floors  • Other.   | Risk <b>√</b><br>N/A           |   |  |                           |   |                     |                 |
| Hazardous Substances:  Cleaning products (for example polish, drain cleaner, etc.)  Other.  | Risk <b>√</b><br>N/A           | Only honsehold products used in the church. User known how to use products safely. All products are safely stored.  |  |                           |   |                     |                 |
| Manual Handling (lifting or carrying):  Bulky or unwieldy furniture  Heavy audio visual or computer equipment  General rubbish that may include breakages (for example, glass)  Other.                          | Risk <b>√</b><br>N/A           | Trolleys available to move heavy objects. Users know how to use the equipment safely. Equipment is checked periodically. Records are kept of the checks made. |  |                           |   |                     |                 |

| What could cause harm? | Tick here<br>if risk or<br>N/A | Existing precautions in place | Additional precautions required | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|------------------------|--------------------------------|-------------------------------|---------------------------------|---------------------------|---|---------------------|-----------------|
| Other:                 | Risk<br>N/A                    |                               |                                 |                           |   |                     |                 |
| Other:                 | Risk<br>N/A                    |                               |                                 |                           |   |                     |                 |
| Other:                 | Risk<br>N/A                    |                               |                                 |                           |   |                     |                 |

#### **Area assessed:**

# 2. Ontside our church

Outside areas of our church (for example, roofs and other high levels, outbuildings, grounds, car park, etc.).

### Who might be harmed?:

Members of the church, employees, volunteers, visitors, Ministers, in fact anyone visiting the church.

| What could cause harm?  | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place  | Additional<br>precautions<br>required                  | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|---|--------------------------------|--|--|---------------------------|---|---------------------|-----------------|
| Trips:  |                                |  |  |                           |   |                     |                 |
| • Uneven footpaths  |                                |  |  |                           |   |                     | 1               |
| <ul> <li>Damaged paving<br/>stones and slabs</li> </ul>   |                                | Footpaths in good<br>condition.<br>No obstructions<br>noted. Steps in<br>good condition. | Lighting defective,                                    |                           |   |                     |                 |
| <ul> <li>Worn damaged or<br/>uneven steps</li> </ul>  | Risk 🗸                         |  |  |                           |   |                     |                 |
| <ul> <li>Kerbs, ledger stones<br/>causing obstruction</li> </ul>  | N/A                            | Handrail<br>provided   | bulb to be replaced.<br>Inspect paths<br>periodically. | 86                        | 30/08/18                                |                     |                 |
| <ul> <li>Protruding tree roots<br/>and undergrowth</li> </ul>   | IVA                            | on steps.<br>All grassed areas<br>are mown on a  | ,  |                           |   |                     |                 |
| <ul> <li>Poor lighting</li> </ul>   |                                | regular basis.   |  |                           |   |                     | 1               |
| <ul> <li>Missing or defective<br/>handrails</li> </ul>  |                                |  |  |                           |   |                     |                 |
| • Other.  |                                | <u> </u>   |  | <del>-</del>              |   |                     | (<br>(<br>(     |
| Slips:  |                                |  |  |                           |   |                     |                 |
| <ul> <li>Poor drainage of footpaths</li> </ul>  |                                |  |  |                           |   |                     |                 |
| <ul> <li>Growth of algae or moss</li> </ul>   |                                |  |  |                           |   |                     |                 |
| <ul> <li>Accumulations of<br/>wet leaves or loose<br/>materials</li> </ul>                                  | Risk 🗸                         | All drainage<br>gullies are clear.<br>britting<br>materials<br>available.                | Keep records of<br>checks made.                        |                           |   |                     |                 |
| • Inadequate precautions<br>for adverse weather<br>(for example snow, ice,<br>etc.)                         | N/A                            |  | Inspect paths periodically.                            | 86                        | 30/08/18                                |                     |                 |
| <ul> <li>Walk-in contaminant<br/>from adverse weather<br/>(for example mud,<br/>rainwater, etc.)</li> </ul> |                                |  |  |                           |   |                     |                 |
| Other.  |                                |  |  |                           |   |                     |                 |

| What could cause harm?   | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place  | Additional precautions required   | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|--|--------------------------------|--|---|---------------------------|---|---------------------|-----------------|
| Access requiring the use of ladders, hatches, sloping roofs, etc.      Restricted access widths around spires      Inadequate protection afforded by parapets      Unprotected roof lights or other fragile roofing material      Damaged ladders, stepladders or access equipment      Inadequate temporary edge protection (such as, guard rails and toe boards)      Other. | Risk <b>√</b><br>N/A           | Adequate, proprietary Stepladder available. Stepladder in good condition/ Checked before use. Stepladder properly stored. Users know how to use it safely. Information on use available. | Make periodic<br>checks<br>of stepladder.<br>Keep records of<br>checks made.  | 86                        | 30/08/18                                |                     |                 |
| Trees:  Damaged or displaced trees  Protruding tree roots Diseased trees Other.  | Risk <b>√</b><br>N/A           | All trees inspected.<br>No defects noted<br>Records are<br>available.  |   |                           |   |                     |                 |
| <ul> <li>Car Park:</li> <li>Entrance and exits not clearly marked</li> <li>Poor lighting</li> <li>Potholes</li> <li>Other.</li> </ul>  | Risk <b>√</b><br>N/A           | Entrance to car park is clearly marked. Lighting is provided and in working order. Lighting is inspected annually. Records of checks made are available.                                 | Make provision for<br>dealing with ice/<br>snow.  | 86                        | 30/08/18                                |                     |                 |
| Faulty or damaged fixed wiring     Faulty, damaged or unauthorised portable electrical equipment     Faulty or damaged extension cables or adaptors     Other.   | Risk <b>√</b><br>N/A           |  | Implement formal<br>checks of portable<br>equipment. Checks<br>to be made by<br>competent person.<br>Records of checks<br>to be kept. | 86-                       | 30/08/18                                |                     |                 |

| What could cause harm?  | Tick here<br>if risk or<br>N/A | Existing<br>precautions in<br>place  | Additional<br>precautions<br>required | Who needs to take action? | When does this need to be completed by? | Tick when completed | Completion date |
|---|--------------------------------|--|---------------------------------------|---------------------------|---|---------------------|-----------------|
| Gas:  |                                |  |                                       |                           |   |                     |                 |
| <ul> <li>Liquefied petroleum<br/>gas (LPG) bottles<br/>incorrectly sited</li> </ul>   | Risk 🗸                         | No LPG is used at<br>the church.   |                                       |                           |   |                     |                 |
| <ul><li>Pipework damaged</li><li>Other.</li></ul>   | N/A                            |  |                                       |                           |   |                     |                 |
| Work Equipment:  Defective or poorly maintained power tools (for example, lawnmowers, strimmers, etc.)  Defective or poorly maintained hand tools (for example, garden shears, hammers, etc.)  Other. | Risk <b>√</b><br>N/A           | No garden<br>machinery is<br>provided for use.   |                                       |                           |   |                     |                 |
| Hazardous Substances:  • Maintenance products (for example, petrol, liquefied petroleum gas, etc.),  • Horticultural products (for example, pesticides, weedkillers, fertilisers, etc.)  • Other.     | Risk <b>√</b><br>N/A           | Only honsehold horticultural products are used. Users know how to use products safely. All products are safely stored. |                                       |                           |   |                     |                 |

#### Want to know more?

We have produced some other useful resources to help you get started or simply check the adequacy of what you have already done. These are all available at:

#### www.methodistinsurance.co.uk/healthandsafety

Note: if you are in Ireland, Northern Ireland, Jersey, Guernsey or the Isle of Man then regional variations might apply. In this instance, you should check the guidance provided by the enforcing authority for your region. This will be freely available on their website.

#### Information in this document

This guidance is provided for information purposes and is general and educational in nature and does not constitute legal advice. You are free to choose whether or not to use it and it should not be considered a substitute for seeking professional help in specific circumstances. Accordingly, Methodist Insurance PLC shall not be liable for any losses, damages, charges or expenses, whether direct, indirect, or consequential and howsoever arising, that you suffer or incur as a result of or in connection with your use or reliance on the information provided in this guidance except for those which cannot be excluded by law. Where this guidance contains links to other sites and resources provided by third parties, these links are provided for your information only. Methodist Insurance is not responsible for the contents of those sites or resources. You acknowledge that over time the information provided in this guidance may become out of date and may not constitute best market practice.

#### Need to contact us?

For further information on health and safety in churches:

Call our Risk Management Advice Line on

#### 0345 600 7531

Monday to Friday, 9am to 5pm (excluding Bank Holidays).

We may monitor or record calls to improve our service.

Email us at: riskadvice@micmail.co.uk



Methodist Insurance PLC 11 York Street Manchester M2 2AW Tel: 0345 606 1331 Fax: 0345 604 6302 www.methodistinsurance.co.uk

Methodist Insurance PLC (MIC) Reg. No. 6369. Registered in England at Benefact House, 2000, Pioneer Avenue, Gloucester Business Park, Brockworth, Gloucester, GL3 4AW, United Kingdom. MIC is authorised by the Prudential Regulation Authority and regulated by the Financial Conduct Authority and the Prudential Regulation Authority. Firm Reference Number 136423.